

CERTIFICATE of TEST

TC6979/2



| | |
|--|--|
| Customer | STIKO BV |
| Contact | Bas Vaartjes |
| Billing Address | Industrieweg 5 9301 LM Roden Netherlands |
| Purchase Order No. / Reference | PO No. . AOE Job No. 6979/2 |
| Date | 04 April 2016 |
| Delivery Address | Industrieweg 5 9301 LM Roden Netherlands |
| Description of Goods PBX SS UD140XA (S/No. .) | |
| Test Details <ul style="list-style-type: none">• External hydrostatic pressure test to 660 Bar for a minimum of 30 minutes• A 2 bar loss of pressure integrity was visually observed on a callibrated pressure indicator gauge and was recorded with a certified calibrated data logger and pressure transducer (s/n 114132) | |
| Tested By | Stuart Mathewson |
| Signed | |
| Date | 09 May 2016 |



Tyrebagger Works, Clinterty, Kinellar
Aberdeen AB21 0TT, United Kingdom

Tel: +44 (0)1224 791001
Fax: +44 (0)1224 791002
Email: admin@alloceans.co.uk
Web: www.alloceans.co.uk

CERTIFICATE of TEST

TC6979/1



| | |
|--|--|
| Customer | STIKO BV |
| Contact | Bas Vaartjes |
| Billing Address | Industrieweg 5 9301 LM Roden Netherlands |
| Purchase Order No. / Reference | PO No. . AOE Job No. 6979/1 |
| Date | 04 April 2016 |
| Delivery Address | Industrieweg 5 9301 LM Roden Netherlands |
| Description of Goods PBX SS100XC (S/No. .) | |
| Test Details <ul style="list-style-type: none">• External hydrostatic pressure test to 440 Bar for a minimum of 30 minutes• A 2.9 bar loss of pressure integrity was visually observed on calibrated pressure indicator gauge and was recorded with a certified calibrated data logger and pressure transducer (s/n114132) | |
| Tested By | Stuart Mathewson |
| Signed | |
| Date | 09 May 2016 |



Tyrebagger Works, Clinterty, Kinellar
Aberdeen AB21 0TT, United Kingdom

Tel: +44 (0)1224 791001
Fax: +44 (0)1224 791002
Email: admin@alloceans.co.uk
Web: www.alloceans.co.uk